

RISK ASSESSMENT: TWO WAY RADIO**Ref. No. WC5**

SECTION:	Waste Collections
SERVICE:	Waste Services
ASSESSMENT REVIEWED:	8 th June 2010, 24 November 2011, 9 th November 2012, January 2015
LOCATION:	Midland Road Depot, Bath
No. OF STAFF:	65
FREQUENCY:	Daily

ASSESSMENT DATE:	17 th April 2009
ASSESSOR'S NAME:	Martin Hellyer
	Pete Wakenshaw
	Mick Wallis
	Laura Gibb
	Geoff Dicker
H&S REP:	
REVIEW DUE:	January 2016

TASKS UNDERTAKEN (associated with this post)	SIGNIFICANT HAZARD (associated with this task)	EXISTING CONTROL MEASURES IN PLACE.	ADDITIONAL CONTROL MEASURES REQUIRED	Risk Rating	Target Date: (for action by)	Completed on: (date and initial)
Use of the two way radio system installed in waste collection vehicles.	Distraction from driving	Operator training and SSOW 06 incorporating instructions to drivers to only use equipment while handbrake applied or the option for loaders to use equipment Keep usage to a minimum Mobile units programmed only to allow calls to predetermined users		Adequate		